Ship Name: ARHONTISA PINELOPI Ship Type: General Dry Cargo Ship

IMO Number: 7371769 Flag: Panama

Date Detained: 06/01/2000 Class Society: American Bureau of Shipping

Port: New Orleans, Louisiana Company(s): Owners, Operators or Managers

**Bravo Ship Management** 

Deficiencies: Code - Category Description

0135 - Minimum safe manning Vessel exceeded maximum voyage length

certificate specified on the minimum safe manning

document.

-----Ship

Name: ARISTEAS P Ship Type: Bulk Carrier

IMO Number: 8315918 Flag: Cyprus

Date Detained: 06/22/2000 Class Society: Nippon Kaiji Kyokai

Port: San Pedro, California Company(s): Owners, Operators or Managers

Barry Shipping Company, Limited

Marmaras Navigation, Ltd.

Deficiencies: Code - Category Description

0630 - Launch arrangt. for

survival craft

Starboard lifeboat would not release properly.

Name: BIG RED BOAT III Ship Type: Passenger Ship

IMO Number: 5367623 Flag: Bahamas

Date Detained: 06/10/2000 Class Society: Lloyd's Register of Shipping

Port: **Houston, Texas** Company(s): Owners, Operators or Managers

**Premier Cruise Lines Ltd** 

**International Shipping Partners** 

Deficiencies: Code - Category Description

0983 - Hull - corrosion Bottom shell plate and structural members

were substantially wasted and pitted. Hull was breeched between frames 38-39 and 35-36,

inboard of the port shaft.

Name: CAPT ALEX Ship Type: Bulk Carrier

IMO Number: 8422917 Flag: Cyprus

Date Detained: 06/30/2000 Class Society: Bureau Veritas

Port: Long Beach, California Company(s): Owners, Operators or Managers

Olympian Silver Shipping Ltd Transmed Shipping, Ltd.

Deficiencies: Code - Category Description

0610 - Lifeboats Starboard lifeboat release mechanism was

inoperable.

ship drill.

Ship Name: CENK KAPTANOGLU Ship Type: Bulk Carrier

IMO Number: 8124955 Flag: Turkey

Date Detained: 06/08/2000 Class Society: Lloyd's Register of Shipping

Port: Vancouver, Washington Company(s): Owners, Operators or Managers

Ileri Denizcilik Ve Ticaret A.S.

Haci Ismail Kaptanoglu

Deficiencies: Code - Category Description

0725 - Fixed fire extinguishing No fixed fire extinguishing system was

installation installed in vessel's cargo holds.

Name: **EDINBURGH** Ship Type: Containership

IMO Number: 7306312 Flag: Greece

Date Detained: 06/06/2000 Class Society: Lloyd's Register of Shipping

Port: Long Beach, California Company(s): Owners, Operators or Managers

Lily Navigation Corp.

Deficiencies: Code - Category Description

1410 - Propulsion main engine Main propulsion engine vital cooling system

was leaking excessively.

1420 - Cleanliness of engine room Hazardous levels of oil in the engine room

Name: **EIRINI** Ship Type: **Bulk Carrier** 

IMO Number: **7525865** Flag: **Panama** 

Date Detained: 06/21/2000 Class Society: American Bureau of Shipping

Port: Baltimore, Maryland Company(s): Owners, Operators or Managers

Makri Shipping, Inc.
Avior Shipping, Inc

Deficiencies: Code - Category Description

1240 - Cargo and other hatchways Cargo hold hatch covers were holed in many

locations, hatch cover gaskets were missing, and many holes were temporarily repaired with duct tape. Cargo hold personnel entry hatches were holed and not weathertight.

Ship Type: **Tankship** (**Not Specified**)

1275 - Ventilators air pipes Numerous ventilator pipes were wasted and

holed; vent closure handwheels were

0630 - Launch arrangt. for Port and Starboard lifeboat davit brakes were

survival craft improperly maintained.

Name: GOLDEN JANE

IMO Number: 9222716 Flag: Panama

Date Detained: 06/07/2000 Class Society: Nippon Kaiji Kyokai

Port: San Francisco, California Company(s): Owners, Operators or Managers

Golden Opportunity Shipping, S.A.

Dorval Kaiun K.K.

Deficiencies: Code - Category

Description

satisfactory abandon ship drill.

Ship Name: HYBUR STAR Ship Type: Refrigerated Cargo Carrier

IMO Number: 5022302 Flag: Antigua and Barbuda

Date Detained: 06/26/2000 Class Society: Not Classed

Port: Tampa, Florida Company(s): Owners, Operators or Managers

St. Maarten Reefers Limited

Deficiencies: Code - Category Description

0135 - Minimum safe manning

certificate

Safe manning document was expired.

0983 - Hull - corrosion Vessel was structurally deficient: main deck,

cargo hatches and covers, and vents were

extensively wasted and holed.

0610 - Lifeboats Starboard lifeboat hull was crushed, and

needed repairs to restore seaworthiness.

0799 - Other (Fire Fighting Main deck fire fighting pipeline was wasted

Equipment) and holed.

Name: J JESSICA Ship Type: Bulk Carrier

IMO Number: 8513429 Flag: Philippines

Date Detained: 06/26/2000 Class Society: Nippon Kaiji Kyokai

Port: Long Beach, California Company(s): Owners, Operators or Managers

Hullwell Shipping, S.A. Mercury Shipping Corp.

Deficiencies: Code - Category Description

0936 - Steering gear Steering gear leaking.

0950 - Electric equipment in Emergency generator would not auto start.
2025 - Abandon ship drills Crew could not perform a satisfactory

abandon ship drill.

room bilge, and diesel oil piping system was

leaking excessively.

0936 - Steering gear Steering gear was leaking oil excessively, and

was unable to swing the rudder to required

**SOLAS** performance standards.

0945 - Emergency lighting, etc Emergency generator was inoperable.

2545 - Reports/analysis of Non-conformity reports were not being sent to

non-conformities, etc. the Company.

2540 - Emergency preparedness There were insufficient procedures to ensure

that the crew could properly operate the

lifeboats.

Ship Name: LIMA Ship Type: Bulk Carrier

IMO Number: 7921813 Flag: Bahamas

Date Detained: 06/15/2000 Class Society: Det Norske Veritas

Port: Vancouver, Washington Company(s): Owners, Operators or Managers

Langford Shipping, S.A. V. Ships (Cyprus) Ltd.

Deficiencies: Code - Category Description

0725 - Fixed fire extinguishing

There was no fixed fire extinguishing system

installation installed in the vessel's cargo holds.

Ship

Name: MARINA Ship Type: General Dry Cargo Ship

IMO Number: 6912712 Flag: Saint Vincent and the Grenadines

Date Detained: 06/27/2000 Class Society: Bureau Veritas

Port: St. Croix, USVI Company(s): Owners, Operators or Managers

Libra Ship Management, Inc

Deficiencies: Code - Category Description

abandon ship drill.

2050 - Operation of machinery The crew was unable to demonstrate the

proper operation of the emergency steering

fighting for use with the self-contained breathing

Name: NAND RATI Ship Type: Bulk Carrier

IMO Number: 8026139 Flag: India

Date Detained: 06/18/2000 Class Society: Indian Register of Shipping

Port: **Big Stone Anchorage, Delaware** Company(s): Owners, Operators or Managers

**Essar Shipping Ltd.** 

Deficiencies: Code - Category Description

0799 - Other (Fire Fighting Fire hydrant valves on forecastle were

**Equipment)** inoperative.

0610 - Lifeboats Port lifeboat engine was inoperative, there

were insufficient food rations, and the provision lockers were not watertight.

0936 - Steering gear Starboard steering gear was leaking hydraulic

oil excessively.

0220 - Certificates of competency The boatswain did not have proper STCW

certification.

2545 - Reports/analysis of Non-conformities were not being reported to

non-conformities, etc. the Company.

Ship Name: NYANZA Ship Type: General Dry Cargo Ship

IMO Number: 7628021 Flag: Bahamas

Date Detained: 06/02/2000 Class Society: Det Norske Veritas

Port: San Juan, Puerto Rico Company(s): Owners, Operators or Managers

**Rockline Investments LTD.** 

Deficiencies: Code - Category Description

0610 - Lifeboats Lifeboat hulls were fractured and

> delaminated, and tillers were seized. Davit blocks were deteriorated beyond 50% of

Ship

**Refrigerated Cargo Carrier** Name: **SHUNKOH** Ship Type:

IMO Number: **8518819** Flag: Singapore

Date Detained: 06/28/2000 Class Society: Nippon Kaiji Kyokai

Port: **Dutch Harbor**, Alaska Company(s): Owners, Operators or Managers

**Shunko Shipping Corporation** 

Deficiencies: Code - Category

Crew could not perform a satisfactory fire 2020 - Fire drills

0680 - Embarkation arrangt. Port and starboard embarkation ladders were

survival craft dry rotted, and incapable of safely supporting

embarking crewmembers.

0735 - Personal equipment - fire

**Self-contained breathing apparatus for** fighting fireman's outfit leaked excessively.

Ship Name: STRIPE Ship Type: Chemical Tankship

IMO Number: 7364027 Flag: Norway

Date Detained: 06/04/2000 Class Society: Det Norske Veritas

Port: Philadelphia, Pennsylvania Company(s): Owners, Operators or Managers

**Hector Shipping** 

Torkel Alendal Rederi AS

Deficiencies: Code - Category Description

2545 - Reports/analysis of Master unaware of non-conformity reporting

non-conformities, etc. procedures.

0999 - Other (Safety In General) Engine room bilge oil was leaking into the

emergency escape trunk.

0720 - Fire fighting equipment Firehose missing in the engine room.

0985 - Bulkheads - corrosion Starboard deck pumproom bulkhead holed.
0960 - Means of escape Emergency escape from accommodations to

lifeboats was locked; engine room emergency escape hatch would not close or latch properly.

0999 - Other (Safety In General) High and low pressure hydraulic lines were

improperly maintained, and in danger of

rupturing.

1835 - Cargo vent system Cargo tanks were leaking gas from numerous

locations.

1825 - Spaces in cargo area Electrical conduit in cargo tanks broken, and

supported by electrical cable only.

1820 - Cargo pumproom / Blank flange in starboard deck pumproom

handling spaces was leaking.

1499 - Other (Prop. & Aux. Numerous leaks and improper temporary Machinery) repairs in overdeck steam line; cargo pump

repairs in overdeck steam line; cargo pump turbine vacuum injector steam line was

improperly repaired.

Name: VILLE DE CAPELLA Ship Type: Containership

IMO Number: 9104914 Flag: Germany

Date Detained: 06/12/2000 Class Society: Germanischer Lloyd

Port: Los Angeles, California Company(s): Owners, Operators or Managers

**NSB Niederelbe Schiffahrtsges** 

Deficiencies: Code - Category Description

1499 - Other (Prop. & Aux. Fuel oil transfer lines in the engine room were

Machinery) leaking excessively at the flanges.